

Photo 1 Hartford Municipal Building Hartford, CTAPK 27 1981 D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission STREETSCAPE, VIEW SOUTHEAST MAR 18



Photo 2 Hartford Co, Municipal Building 1981 Hartford. CT D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission PLAZM. VIEW NORTHEAST



Photo 3 Hartford Co., Municipal Building Hartford, CT App 25/7198 Negative: Connecticut Historical Commission PROSPECT STREET ELEVA-TION. VIEW NORTHWEST



Photo 4 Hartford Co, Municipal Building Hartford, CT App D. Ransom Photo, 2677/98/ Negative: Connecticut Historical Commission MAIN AND ARCH STREETS ELEVATIONS. VIEW NE



Photo 5 Hartford Co., Municipal Building Hartford, CTAPP D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission

NORTH ELEVATION WITH STEGOSAURUS. VIEW S.



Photo 6 Hartford Municipal Building A. Hartford, CT D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission ATRIUM, VIEW EAST



Photo 7 Hartford Co., Municipal Building Hartford, CT D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission STAIRWAY. VIEW NORTH-

MAR 1 8 198

EAST, 2ND-FLOOR LEVEL



Photo 8 Hartford Co.
Municipal Building
Hartford, CT
D. Ransom Photo, 6/79
Negative: Connecticut
Historical Commission

Negative: Connecticut Historical Commission COFFER AND SCULPTURE, VIEW SOUTHEAST

MAR 1 8 1981



Photo 9 Hartford
Municipal Building Hartford, CT D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission FUNCTION ROOM. VIEW NORTH




Photo 10 Hartford Municipal Building Hartford. CT D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission

IRON HEATING COLLS, VIEW NORTHWEST



Photo 11 Hartford (Municipal Building Hartford, CT D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission

LIONS. VIEW NORTHEAST

8 198



Photo 12 Hartford Co., Municipal Building Hartford, CT D. Ransom Photo, 6/79 Negative: Connecticut Historical Commission ATRIUM LIGHTING. VIEW NORTHEAST MAR 1 8 1981